File View Actions

Si2_CsI1_S1
Counts = 4.863000E+03 Counts Above Th. = 4
NO Compression



Si2_CsI1_S2
Counts = 5.721000E+03 Counts Above Th. = 5
NO Compression



Si2_CsI1_S3
Counts = 0.000000E+00 Counts Above Th. = 0
NO Compression



Si2_CsI1_S4
Counts = 5.690000E+03 Counts Above Th. = 5
NO Compression



Si2_CsI1_S5
Counts = 1.451300E+04 Counts Above Th. = 1
NO Compression



Si2_CsI1_S6
Counts = 5.885000E+03 Counts Above Th. = 5
NO Compression



Si2_CsI1_S7
Counts = 5.080000E+03 Counts Above Th. = 5
NO Compression



Si2_CsI1_S8
Counts = 6.838000E+03 Counts Above Th. = 6
NO Compression