File View Actions

Si6_CsI2_S1
Counts = 8.815000E+03 Counts Above Th. =
NO Compression

Si6_CsI2_S2
Counts = 9.251000E+03 Counts Above Th. =
NO Compression

Si6_CsI2_S3
Counts = 1.530200E+04 Counts Above Th. =
NO Compression

Si6_CsI2_S4
Counts = 9.157000E+03 Counts Above Th. =
NO Compression



Si6_CsI2_S5
Counts = 1.481800E+04 Counts Above Th. =
NO Compression

Si6_CsI2_S6
Counts = 8.419000E+03 Counts Above Th. =
NO Compression

Si6_CsI2_S7
Counts = 7.003000E+03 Counts Above Th. =
NO Compression

Si6_CsI2_S8
Counts = 7.381000E+03 Counts Above Th. =
NO Compression